

# Closure Report

## Site Description

Site Name:	Lentini 1 Federal Battery
Company:	Chevron USA
Legal Description:	U/L F, Section 1, T23S, R28E
County:	Eddy County, NM
GPS Coordinates:	N 32.33701 W-104.04275

## Release Data

Date of Release:	1/6/18
Type of Release:	Produced water
Source of Release:	Compromised injection line
Volume of Release:	39.74 bbls
Volume Recovered:	10 bbls

## Remediation Specifications

Remediation Parameters:	Excavated the entire leak area to a depth of 4 feet. Placed an impermeable liner in the excavated area. Backfilled the site with clean soil.	
Remediation Activities:	6/11/19 to 6/19/19	
Plan Sent to OCD:	6/20/18	Email from Cliff Brunson to Mike Bratcher
OCD Approval of Plan:	7/26/18	Email from Mike Bratcher to Cliff Brunson
Plan Sent to BLM:	6/20/18	Email from Cliff Brunson to Shelly Tucker
BLM Approval of Plan:	7/11/18	Email from Shelly Tucker to Cliff Brunson

## Supporting Documentation

Initial C-141	Signed 1/18/17
C-141, page 6	Signed and included
Site Diagram	June 2018
Pictures	Remediation pictures prior to and after backfill

## Request for Closure

Based on the completion of the remediation plan, BBC International, Inc. requests closure approval from NMOCD.

Cliff Brunson, President, BBC International, Inc.


06/21/2019

# Chevron, Lentini Federal 1 Battery

Leak date: 01/07/2018  
Eddy County, NM  
API# 30-015-27535

**Legend**

-  4 ft Excavation with liner
-  Cardinal sample points
-  Leak Area
-  Sample points



Google Earth

© 2018 Google



70 ft

Chevron, Lentini Federal 1 Battery

Sample points

SP1, N 32.33716 W-104.04267

SP2, N 32.33705 W-104.04272

SP3, N 32.33694 W-104.04277

SP4, N 32.33687 W-104.04283

NORTH, N 32.33723 W-104.04263

SOUTH, N 32.33683 W-104.04286


EAST, N 32.33698 W-104.04268

WEST, N 32.33703 W-104.04279











Incident ID	
District RP	2RP-4581
Facility ID	
Application ID	

### Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

**Closure Report Attachment Checklist:** *Each of the following items must be included in the closure report.*

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Amy Barnhill Title: Waste & Water Specialist  
 Signature: *Amy Barnhill* Date: 6-24-19  
 email: abarnhill@chevron.com Telephone: (432) 687-7108

**OCD Only**

Received by: \_\_\_\_\_ Date: \_\_\_\_\_

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: *Bradford Billings* Date: 10/30/2019  
 Printed Name: Bradford Billings Title: E. Spec. A