

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2011830287
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Transwestern Pipeline Company	OGRID 329750
Contact Name: Larry Campbell	Contact Telephone: 575 625 8022
Contact email: larry.campbell@energytransfer.com	Incident # (assigned by OCD)
Contact mailing address: 6381 North Main St. Roswell, NM 88201	

Location of Release Source

Latitude 33.919052 Longitude -105.326890
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Corona Compressor Station	Site Type: Compressor Station
Date Release Discovered: 4/14/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
F	36	T4S	R15E	Lincoln

Surface Owner: X State ☐ Federal ☐ Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
X Natural Gas	Volume Released (Mcf) 495 mcf	Volume Recovered (Mcf) 0
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: The facility had an emergency shutdown (ESD) due to the faulty pipeline gasket.

