

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Aaron Pina, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Mean Green 23 Fed 1H Battery	Facility Type	Battery
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-025-41292

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	23	26S	34E	25'	FSL	330'	FEL	Lea

Latitude_32.0216446_ Longitude_103.4332657_ NAD83

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	62bbbls	Volume Recovered	62bbbls
Source of Release	Produced Water Tank	Date and Hour of Occurrence	July 27, 2018 @ 8:00 PM	Date and Hour of Discovery	July 27, 2018 @ 8:00 PM
Was Immediate Notice Given?	☒ Yes ☐ No ☐ Not Required	If YES, To Whom?	Olivia Yu, OCD Chistina Hernandez, BLM		
By Whom?	Brett Fuls, EHS Representative	Date and Hour	July 29, 2018 @ 9:42 PM		
Was a Watercourse Reached?	☐ Yes ☒ No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.*	N/A				

RECEIVED

By Olivia Yu at 8:56 am, Aug 20, 2018

Describe Cause of Problem and Remedial Action Taken.*

Power outage caused pump to go down on high discharge, wells were shut in but this well auto started and ran tank levels over. Truck arrived on site and immediately started pulling tank levels down.

Describe Area Affected and Cleanup Action Taken.*

Approximately 62bbbls produced water was released into lined containment. All 62bbbls produced water was recovered from lined containment. Containment liner was inspected for holes and none were found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		Approved by Environmental Specialist: 	
Title: Field Admin Support		Approval Date: 8/20/2018	Expiration Date:
E-mail Address: Sheila.Fisher@divn.com		Conditions of Approval:	Attached ☐
Date: 8/2/18	Phone: 575.748.1829	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1823231809

Mean Green 23 Fed 1H Battery

62bbbs PW_7.27.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sheila Fisher
Map is current as of: 08-Aug-2018



Miles

0 0.01 0.02 0.04 1: 1,779



From: Fulks, Brett
To: [Yu, Olivia, EMNRD](#); [Hernandez, Christina, EMNRD](#); [Tucker, Shelly](#)
Cc: [Fisher, Sheila](#); [DeLaRosa, Dana](#); [Pina, Aaron](#); [Shoemaker, Mike](#)
Subject: Mean Green 23 Fed 1H Battery (API #30-025-41292) Release Notification
Date: Sunday, July 29, 2018 9:41:41 PM
Attachments: image001.png

Good afternoon,

Devon identified the following release at approximately 3:59 AM MST on 07/28/18.

1. Mean Green 23 Fed 1H Battery (API #30-025-41292)

A produced water tank overflowed, releasing approximately 62 bbls of produced water into lined secondary containment. All fluid was recovered from the secondary containment.

A C-141 will be prepared and submitted with GPS coordinates of the area affected.

Thanks,

Brett Fulks
EHS Representative

Devon Energy Corporation

6488 Seven Rivers Highway
Artesia, New Mexico 88210
575 748 1844 Direct
432 301 3223 Mobile



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.