District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2021846438
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

OGRID

Contact Name Co.			Contact Telephone				
Contact email				Incident # (assigned by OCD)			
Contact mail	ing address						
			Location	of Re	lease So	ource	
Latitude			(NAD 83 in de	L ecimal degre	ongitude _ ees to 5 decim	al places)	
Site Name					Site Type		
Date Release	Discovered			1	API# (if app	licable)	
Unit Letter	Section	Township	Range		Coun	ty	7
Surface Owner Crude Oil	Material	Federal Tri	Nature and	d Volu	me of F	justification for th	ne volumes provided below) overed (bbls)
Produced							overed (bbls)
	w atei	Volume Released (bbls) Is the concentration of total dissolved solids (TDS in the produced water >10,000 mg/l?			s (TDS)	Yes 1	
Condensa	ite	Volume Released				Volume Recovered (bbls)	
Natural G	ias	Volume Released (Mcf)			Volume Recovered (Mcf)		
Other (des	scribe)	Volume/Weight Released (provide units)			Volume/Weight Recovered (provide units)		
Cause of Relo	ease						

-			-		0
v	aa	a	7	0	
	uz	C	Air .	v	
_	· O	_	_		

Incident ID	NRM2021846438
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the responsib	le party consider this a major release?
☐ Yes ☐ No		
If YES, was immediate no	otice given to the OCD? By whom? To whon	? When and by what means (phone, email, etc)?
	Initial Res	oonse
The responsible p	party must undertake the following actions immediately un	less they could create a safety hazard that would result in injury
☐ The source of the rele	ease has been stopped.	
☐ The impacted area ha	s been secured to protect human health and the	environment.
Released materials ha	we been contained via the use of berms or dike	s, absorbent pads, or other containment devices.
<u> </u>	ecoverable materials have been removed and n	
If all the actions described	d above have <u>not</u> been undertaken, explain wh	;
has begun, please attach	a narrative of actions to date. If remedial effe	Ediation immediately after discovery of a release. If remediation orts have been successfully completed or if the release occurred se attach all information needed for closure evaluation.
		of my knowledge and understand that pursuant to OCD rules and
public health or the environment failed to adequately investigation	ment. The acceptance of a C-141 report by the OCI ate and remediate contamination that pose a threat t	does not relieve the operator of liability should their operations have groundwater, surface water, human health or the environment. In onsibility for compliance with any other federal, state, or local laws
Printed Name:		Γitle:
Signature: GM	3_	Date:
		elephone:
OCD Only		
Received by:Ram	iona Marcus	ate: _8/5/2020

NRM2021846438

Location:	PLU CVX JV BS 013		
Spill Date:	7/18/2020		
	Area 1		
Approximate A	rea =	270.00	sq. ft.
Average Satura	tion (or depth) of spill =	48.00	inches
Average Porosi	ty Factor =	0.20	
	VOLUME OF LEAK		
Total Crude Oil	=	6.23	bbls
Total Produced	Water =	32.72	bbls
	Area 2		
Approximate A	rea =	380.00	sq. ft.
Average Satura	tion (or depth) of spill =	5.00	inches
Average Porosi	ty Factor =	0.20	
	VOLUME OF LEAK		
Total Crude Oil	=	0.90	bbls
Total Produced	Water =	4.74	bbls
	TOTAL VOLUME OF LEAK		
Total Crude Oil	=	7.13	bbls
Total Produced	Water =	37 46	hhls

TOTAL VOLUME OF LEAK				
Total Crude Oil =	7.13	bbls		
Total Produced Water =	37.46	bbls		
TOTAL VOLUME RECOVERED				
Total Crude Oil =	0.08	bbls		
Total Produced Water =	0.40	bbls		