

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Incident ID	NRM2022459251
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	OXY USA INC.	OGRID	16696
Contact Name	WADE DITTRICH	Contact Telephone	(575) 390-2828
Contact email	WADE_DITTRICH@OXY.COM	Incident # (assigned by OCD)	
Contact mailing address	PO BOX 4294; HOUSTON, TX 77210		

### Location of Release Source

Latitude N 32.19831 Longitude W 103.98027  
*(NAD 83 in decimal degrees to 5 decimal places)*

Site Name	CEDAR CANYON 21-22 FED 34H	Site Type	
Date Release Discovered	7-25-20	API# (if applicable)	

Unit Letter	Section	Township	Range	County
M	22	24S	29E	EDDY COUNTY, NM

Surface Owner:  State  Federal  Tribal  Private (Name: OXY, USA INC.)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 20 BBLS	Volume Recovered (bbls) 0 BBLS
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 30 BBLS	Volume Recovered (bbls) 0 BBLS
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

6 INCH POLY FLOW LINE FAILURE

Form C-141

State of New Mexico  
Oil Conservation Division

Page 2

Incident ID	NRM2022459251
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? <b>THE RELEASE IS GREATER THAN 25 BBLS</b>
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? <b>YES, BY WADE DITTRICH, TO MIKE BRATCHER, ROBERT HAMLET, VICTORIA VENEGAS 7-27-20 VIA E-MAIL</b>	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why:  	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Wade Dittrich</u>	Title: <u>Environmental Coordinator</u>
Signature: <u></u>	Date: <u>8-6-2020</u>
email: <u>wade_dittrich@oxy.com</u>	Telephone: <u>(575) 390-2828</u>
<b><u>OCD Only</u></b>	
Received by: <u>Ramona Marcus</u>	Date: <u>8/11/2020</u>

Location of spill: Cedar Canyon 21-22 Fed 34H

Date of Spill: 7/25/2020

Site Soil Type: Silt (caliche)

Average Daily Production: BBL Oil BBL Water

Total Area Calculations							
Total Surface Area	width		length		wet soil depth	oil (%)	
Rectangle Area #1	130 ft	X	142 ft	X	1 in	40%	
Rectangle Area #2	65 ft	X	74 ft	X	1 in	40%	
Rectangle Area #3	5 ft	X	115 ft	X	1 in	40%	
Rectangle Area #4	0 ft	X	0 ft	X	0 in	0%	
Rectangle Area #5	0 ft	X	0 ft	X	0 in	0%	
Rectangle Area #6	0 ft	X	0 ft	X	0 in	0%	
Rectangle Area #7	0 ft	X	0 ft	X	0 in	0%	
Rectangle Area #8	0 ft	X	0 ft	X	0 in	0%	

Porosity 0.16 gal per gal

**Saturated Soil Volume Calculations:**

		H2O	OIL	
Area #1	18460 sq. ft.	923 cu. ft.	615 cu. ft.	
Area #2	4810 sq. ft.	120 cu. ft.	80 cu. ft.	
Area #3	575 sq. ft.	14 cu. ft.	10 cu. ft.	
Area #4	0 sq. ft.	cu. ft.	cu. ft.	
Area #5	0 sq. ft.	cu. ft.	cu. ft.	
Area #6	0 sq. ft.	cu. ft.	cu. ft.	
Area #7	0 sq. ft.	cu. ft.	cu. ft.	
Area #8	0 sq. ft.	cu. ft.	cu. ft.	
Total Solid/Liquid Volume:	23,845 sq. ft.	1,058 cu. ft.	705 cu. ft.	

**Estimated Volumes Spilled**

	H2O	OIL	
Liquid in Soil:	30.1 BBL	20.1 BBL	
Liquid Recovered :	0.0 BBL	0.0 BBL	
Spill Liquid	30.1 BBL	20.1 BBL	
Total Spill Liquid:	50.2		

**Recovered Volumes**

Estimated oil recovered: 0.0 BBL  
 Estimated water recovered: 0.0 BBL

Soil Type	Porosity
Clay	0.15
Peat	0.40
Glacial Sediments	0.13
Sandy Clay	0.12
Silt	0.16
Loess	0.25
Fine Sand	0.16
Medium Sand	0.25
Coarse Sand	0.26
Gravelly Sand	0.26
Fine Gravel	0.26
Medium Gravel	0.25
Coarse Gravel	0.18
Sandstone	0.25
Siltstone	0.18
Shale	0.05
Limestone	0.13
Basalt	0.19
Volcanic Tuff	0.20
Standing Liquids	