

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NMAP1825641927
District RP	2RP-4970
Facility ID	fMAP1825641074
Application ID	pMAP1825641619

## Release Notification

### Responsible Party

Responsible Party: Lucid Energy Group (DBA: Agave Energy)	OGRID: 147831
Contact Name: Kerry Egan	Contact Telephone: 575-810-6021
Contact email: Kegan@lucid-energy.com	Incident # (assigned by OCD)
Contact mailing address: 201 South Fourth Street Artesia, NM 88210	

### Location of Release Source

Latitude 32.655099° Longitude -104.487621°  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Boyd X Battery	Site Type: Tank Battery (Gathering pipeline at a Tank Battery)
Date Release Discovered: 6-29-2018	API# (if applicable)

Unit Letter	Section	Township	Range	County
O	16	19S	25E	Eddy

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf): Unknown	Volume Recovered (Mcf): N/A
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Corrosion on meter run header resulted in a pinhole leak.



State of New Mexico  
Oil Conservation Division

Incident ID	NMAP1825641927
District RP	2RP-4970
Facility ID	fMAP1825641074
Application ID	pMAP1825641619

<p>Was this a major release as defined by 19.15.29.7(A) NMAC?</p> <p><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</p>	<p>If YES, for what reason(s) does the responsible party consider this a major release?</p> <p>The total volume of gas released is unknown, but is not suspected to have constituted a major release. There is no evidence to indicate that any liquid was released at major reporting levels either.</p>
<p>If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?</p>	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<p><input checked="" type="checkbox"/> The source of the release has been stopped.</p> <p><input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.</p> <p><input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.</p> <p><input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.</p>	
<p>If all the actions described above have <u>not</u> been undertaken, explain why:</p> <p>There were no freestanding liquids to contain or recover. The area impacted by the gas release is secured within the battery's containment berm, and fenced off to prevent entrance by the public or wildlife.</p>	
<p>Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.</p>	
<p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>	
<p>Printed Name: <u>Kerry Egan</u></p> <p>Signature: <u></u></p> <p>email: <u>Kegan@lucid-energy.com</u></p>	<p>Title: <u>Environmental Compliance Manager</u></p> <p>Date: <u>9/11/2018</u></p> <p>Telephone: <u>575-810-6021</u></p>
<p><b><u>OCD Only</u></b></p> <p>Received by: <u></u> Date: <u>09/13/18</u></p>	