

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

DISTRICT OFFICE MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company A. N. SPANEL - W. O. HEINZE		Address Room 6420-350 Fifth Avenue, New York 1, New York				
Lease Santa Fe-Pacific RR	Well No. 1-9617	Unit Letter H	Section 27	Township 4 North	Range 11 West, N.M.P.M.	
Date Work Performed 9-23-59	Pool Wildcat			County Catron		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):
☒ Plugging Plugged & Abandoned Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

T.D. 5392, Granite - Drill Pipe Measurement

Ran Schlumberger to T. D.

Filled hole with drilling mud

Plug # 1: 50 sacks Portland Cement-Gilsonite 50-50 mix 2% CaCl₂
From 4200 - 4075.

Plug # 2: 50 sacks as above from 3200 to 3075.

Plug # 3: 30 sacks as above from 360 to 307 - Bottom of
surface pipe.Plug # 4: 25 sacks Portland Cement packed in top of
surface pipe.

Name and Location of test marked in fresh cement. 4" pipe
cemented in surface csg - 6' above ground and 6' in cement.
Brass marker to be braised to 4" pipe later.

Witnessed by H. F. Addington	Position Consulting Engineer	Company A.N. Spanel-W.O. Heinze
---------------------------------	---------------------------------	------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 7412 Corrected	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>Charles H. Garcia</i>	Name <i>John H. Burton</i>
Title <i>Chief of Cas. Inspector</i>	Position Santa Fe, N. Mexico Authorized Agent for
Date <i>Aug 7, 1960</i>	Company A. N. Spanel - W. O. Heinze

Sept. 3, 1959 10:30 AM

Verbal authorization requested by C.H. Kearny
Geologist for Spanel - Hevige to plug & abandon
Spanel - Hevige S. Fr. - Pac. R.R. Well # 1-9617
located 2080' FNL and 560' FEL Sec. 27
T 4 North R 11 West NMPM Catron County.

13 $\frac{3}{4}$ " casing set at 328' and cement circulated

T.D. 3819'

Water encountered 3205' - 3245'

No show oil or gas.

Plugging program set by Wutter

Cement plug - 3200 - 3250

Cement plug - 328' 20 sacks

Cement plug - Surface 20 sacks

Required Marker set in surface plug.

John Burton to file required forms

~~For~~ Verbal authorization to plug granted

J.K.