

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES OFFICE OCC
DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY
1963 OCT 1 PM 1:23

Land Office Santa Fe

Lease No. NM 0161297

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 17, 19~~62~~63

Well No. 1-A is located 2220 ft. from N line and 460 ft. from E line of sec. 36

SENE 36

12N

9W

NMPM

($\frac{1}{4}$ Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Wildcat

(Field)

Valencia

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the ~~ground~~ floor above sea level is 7162 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)



Well was plugged as follows:

TD 432 - 4 $\frac{1}{2}$ " hole

8 $\frac{1}{2}$ sx cement 432 - 332

1 $\frac{1}{2}$ sx cement 18' - 0

Marker erected at the site



U. S. GEOLOGICAL SURVEY
FACILITY NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company OBIE SHAW

Address XXX 323 Vine Street

Evansville, Indiana

By Robert E. Lanth

Title Consulting Geologist