



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Allottee _____

Lease No. 14-20-602-5580

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Drill Stem Test

RECEIVED

SURVEY
MEXICO

Operating: Pueblo of Acoma #1 (INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 4, 1960

Well No. 1 is located 1900 ft. from S line and 1900 ft. from E line of sec. 2

NW 1/4 of SE 1/4 of Sec. 2 7 N 7 W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wildcat
(Field)

Valencia
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is Appx. 6336 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Drill Stem Test No. 2 - Run by Halliburton on 3-2-60. 4486' - 4526'. 5/8" x 1" chokes, tool open 3 hours. 30 minute initial shut in pressure 1755#, 30 minute final press. 1575#. Hyd. press. in 2265#, out 2235#. Temperature 130°F - Recovered 670' fluid. 430' gas out mud, chlorides 450 p.p.m. 240' water - chlorides 1600 p.p.m.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sun Oil Company

Address Box 2792

Odessa, Texas

By [Signature]

Title Area Superintendent