

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-007-20302
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: VPR E
8. Well No. 34 WDW
9. Pool name or Wildcat Stubblefield Canyon – Vermejo Gas

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐ X Water Disposal	
2. Name of Operator EL PASO ENERGY RATON, L.L.C.	8. Well No. 34 WDW
3. Address of Operator PO BOX 190, RATON, NM 87740	9. Pool name or Wildcat Stubblefield Canyon – Vermejo Gas
4. Well Location Unit Letter <u>A</u> : <u>1268.5</u> feet from the <u>North</u> line and <u>368.2</u> feet from the <u>East</u> line Section <u>05</u> Township <u>31N</u> Range <u>19E</u> NMPM Colfax County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 8573.6' (GL)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Mechanical Integrity Test** ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well bore diagram of proposed completion or recompilation.

08/12/02 Performed MIT on tubing/casing annulus. Leed Energy kill pump truck pressure annulus to 500 psi.
Ran chart recorder. (Chart attached.) Held 500 psi for 30 minutes. Pressure test OK.
Witnessed by Bryan Olmstead; Sierra, Don Lankford; El Paso Energy Raton, LLC, and
Roy Johnson: NMOCD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donald R. Lankford / Shirley A. Mitchell TITLE Engineer DATE 08/20/02
Type or print name Donald R. Lankford by Shirley A. Mitchell, Field Adm. Specialist Telephone No. (505) 445-6721
(This space for State use)

APPROVED BY [Signature] TITLE **DISTRICT SUPERVISOR** DATE 8/23/02
Conditions of approval, if any: