

SUGGESTED FIELD DATA SHEET (Not Required To File)						SW/4 OF NE/4	
Type Test ☐ Initial ☐ Annual ☐ Special						Test Date	
Company TRANS PECOS RESOURCES INC.						Lease No. or Serial No.	
Field 						Allottee	
Completion Date						Unit	
Total Depth						Part of Lease Tract LATIGO RANCH	
Plug Back To						Well No.	
Elevation						1	
Casing Size Wt. d Set At Perforations From To						Sec. Twp. Blk. Rge. Sur. 2 9N 23E	
Type Completion (Describe)						County or Parish GUADALUPE	
Producing Thru Reservoir Temp. F Mean Annual Temp. F Surface Press. P ₀						State	
L H G _g % CO ₂ % H ₂ % H ₂ S						Prover Meter Run Tops	

DATE	ELAP. TIME	Wellhead Working Pressure			METER OR PROVER				REMARKS
Time of Reading	Hrs.	Tbq. Pstg.	Csg. Pstg.	Temp. F	Pressure Pstg.	Diff.	Temp. F	Orifice	(Include liquid production data: Type-A.P. I. Gravity-Amount)
4-23-82		LEFT SHOP AT 1000 HRS. - STOP TO LET TRUCK COOL DOWN. BLOWING OIL. 1345 HRS. STOP IN FT. SUMNER TO EAT. ON LOCATION AT 1600 HRS. RIG UP BY 2000 HRS.							
4-24-82		0800 HRS. START FLOW TEST 0935 HRS. SHUT IN WELL PULLING CREW SWABBED REQUESTED WE STAY ON LOCATION IN CASE WELL CAME IN. SHUT IN AT 1800 HRS. CHECK DEAD WEIGHT.							
2000		125							
2100		70							
2200		160							
2300		200							
2400		270							
4-25-82									
0100		350							
TIME CHANGE									
0300		400							
0400		435							
0500		460							
0600		500							
0700		525							
0800		545							
0900		FLOWED WELL TO PIT THRU BY PASS TRYING TO RECOVER FLUID.							
0920		WELL SHUT IN.							
1000		231							
1100		250							
4-25-82		1100 HRS. START SWABBING AND FLOWING WELL- REQUESTED WE STAY ON LOCATION IN CASE WELL CAME IN - WELL SHUT IN FOR BUILD UP							
1800									
1900									