



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. NM 0973
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

SEP 1 1954

Well No. 1 is located 1980 ft. from SN line and 1978 ft. from E line of sec. 26.

26 (1/4 Sec. and Sec. No.) SN (Twp.) 23 E (Range) _____ (Meridian)
Wildcat (Field) Guadalupe (County or Subdivision) New Mexico (State or Territory)

RECEIVED

SEP 13 1954

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cement plug from bottom of hole to 990 feet, drilling mud to 150 feet of top, cement to top. Capped 4 feet, 4 inch pipe placed as marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company FY Sumner O.G.

Address _____

By [Signature]
Title _____