



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office NM
Lease No. 0973
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 3 is located 1980 ft. from S line and 1978 ft. from W line of sec. 26
26 N 3E NMPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 463 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Int surface pipe 1 inch at 463 10 3/4
1 1/2 inch casing

This form was filed
DELINQUENT

Submission pursuant to Oil and Gas
Operating Regulations is required.

Approved for record purposes.

MAR 2 1953

Date

H. A. Dubont
District Engineer

RECEIVED
FEB 25 1953
U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John H. ...

Address Key ...

By ...

Title ...

ILLEGIBLE