

INVESTIGATION REPORT
(One Copy Must Be Filed With Each Completion Report.)

1. FIELD NAME	2. LEASE NAME	Well Number
	BDCDGV	1833-261 K
3. OPERATOR		
AMOCO Production Co.		
4. ADDRESS		
P.O. Box 606, Clayton, N.M. 88415		
5. LOCATION	County	
T18N R 33E, Sec 26 "K"		

[illegible]

If additional space is needed, use the reverse side of this form.

17. Is any information shown on the reverse side of this form? ☐ yes ☒ no

18. Accumulative total displacement of well bore at total depth of 2770 feet = 31.24 feet.

19. Inclination measurements were made in - ☐ Tubing ☐ Casing ☐ Open hole ☒ Drill Pipe

20. Distance from surface location of well to the nearest lease line _____ feet.

21. Minimum distance to lease line as prescribed by field rules _____ feet.

22. Was the subject well at any time intentionally deviated from the vertical in any manner whatsoever? No

(If the answer to the above question is "yes", attach written explanation of the circumstances.)

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the above results.

Drilling Contractor Baker & Taylor Drilling

By David P. Myers

Subscribed and sworn to before me this 7 day of November 1984



SUE BAER
Notary Public, State of Texas
My Commission Expires 6/9/1

Notary Public

My Commission Expires:

Potter County, Texas