

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2033-162H Field: Bravo Dome

Location: 1986 FSL x 1980' FSL T20N R83E Sec 16

<u>DEPTH</u>	<u>ANGLE INCLINATION DEGREES</u>
<u>252'</u>	<u>1/2 °</u>
<u>448'</u>	<u>1/4 °</u>
<u>760'</u>	<u>1/4 °</u>
<u>1262'</u>	<u>3/4 °</u>
<u>1754'</u>	<u>3/4 °</u>
<u>2249'</u>	<u>3/4 °</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young (Amoco)

Kurt L. Lutz
Title: MWS Toolpusher