


INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415
Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-131G Field: Bravo Dome
Location: 2035' FEL X 1936' FNL T21N R32E SEC 13, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>458</u>	<u>1°</u>
<u>642</u>	<u>1°</u>
<u>1113</u>	<u>1.25°</u>
<u>1587</u>	<u>1.25°</u>
<u>2059</u>	<u>1°</u>
<u>2438</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: C. J. L. L. L.