

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-141G Field: Bravo Dome

Location: 1963' FEL X 1959' FNL T21N, R32E, SEC 14, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>215</u>	<u>1/2</u>
<u>461</u>	<u>1 1/2</u>
<u>680</u>	<u>1/4 °</u>
<u>1117</u>	<u>1/4 °</u>
<u>1591</u>	<u>3/4 °</u>
<u>2065</u>	<u>3/4 °</u>
<u>2425</u>	<u>3/4 °</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert C. Berry
FOR JIM KINDER

C. J. Redman
Title: T-R, Section