

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415


Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-250 Field: Bravo Dome

Location: 1949' FEL X 1946' ENL T2IN R32E, SEC 25, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>470</u>	<u>1/2</u>
<u>649</u>	<u>1</u>
<u>1004</u>	<u>1</u>
<u>1458</u>	<u>1</u>
<u>1955</u>	<u>1</u>
<u>2500</u>	<u>1 1/2</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: Area Toolpusher