

OIL CONSERVATION DIVISION
RECEIVED

INCLINATION REPORT

'93 JUN 24 AM 8 55

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-051G Field: Bravo Dome

Location: 1793' FEL x 2024' FNL, T21N, R33E, SEC05, UNIT-G

| <u>DEPTH</u> | <u>ANGLE INCLINATION DEGREES</u> |
|---------------|--------------------------------------|
| <u>437</u> | <u>1/4°</u> |
| <u>684</u> | <u>3/4°</u> |
| <u>1148</u> | <u>1°</u> |
| <u>1619</u> | <u>1°</u> |
| <u>2568</u> | <u>1°</u> |
| <u> </u> | <u> </u> |
| <u> </u> | <u> </u> |

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Monte J. [Signature]

[Signature]
Title: Area Toolpusher