

OIL CONCEPTS NEW SIGN
RECEIVED

'93 JU 16 AM 8 38

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-0716 Field: Bravo Dome

Location: 1777' FEL X 1984' FNL T21N, R33E, SEC 07, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>214'</u>	<u>1/4°</u>
<u>490'</u>	<u>1/4°</u>
<u>703'</u>	<u>1/2°</u>
<u>1150'</u>	<u>3/4°</u>
<u>1623'</u>	<u>2°</u>
<u>1718'</u>	<u>2 1/4°</u>
<u>1813'</u>	<u>2°</u>

2129' 1 3/4°
2505' 1 1/2°

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Monte Wilson

Billy Dumbly
Title: SITON Tool Pusher