

'93 JUL 4 AM 8 41

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-081G Field: Bravo Dome

Location: 1762' FEL X 1971' FNL T21N, R33E, SEC 08, UNIT G

DEPTH	ANGLE INCLINATION DEGREES		
<u>215'</u>	<u>1/4°</u>	1563'	2 3/4°
<u>493'</u>	<u>1/4°</u>	1658'	3°
<u>718'</u>	<u>1/2°</u>	1721'	3°
<u>1152'</u>	<u>1°</u>	1847'	2 3/4°
<u>1373'</u>	<u>1.5°</u>	2036'	2 1/4°
<u>1468'</u>	<u>2°</u>	2471'	2°

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: SITON Tool Pusher