

OIL CONSERVATION DIVISION
RECEIVED


INCLINATION REPORT

93 JU 9 AM 8 41

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415
Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No 2133-141G Field: Bravo Dome
Location: ~~1974~~ 1974' FEL X 2024' FNL T21N, R33E, SEC 14, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>460</u>	<u>1°</u>
<u>644</u>	<u>3/4°</u>
<u>1114</u>	<u>3/4°</u>
<u>1587</u>	<u>1/2°</u>
<u>1965</u>	<u>1°</u>
<u>2345</u>	<u>1°</u>
<u>2630</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.



B. J. Hedger
Title: J.P.