

93 JUL 22 AM 9 13



INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-181G Field: Bravo DomeLocation: 2012' FEL X 1979' ENL T21N R33E SEC 18 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>214</u>	<u>1/4</u>
<u>441</u>	<u>1/4</u>
<u>695</u>	<u>1 1/2</u>
<u>1159</u>	<u>1</u>
<u>1592</u>	<u>1</u>
<u>2105</u>	<u>1 1/2</u>
<u>2435</u>	<u>1 1/2</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.


Title: T.P.