

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415


Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No 2133-26 Field: Bravo Dome

Location: 2007' FEL X 1991' FSL T21N, R33E, SEC 26, UNIT J

DEPTH	ANGLE INCLINATION DEGREES
<u>473'</u>	<u>$3/4^{\circ}$</u>
<u>688'</u>	<u>$1/2^{\circ}$</u>
<u>1154'</u>	<u>$3/4^{\circ}$</u>
<u>1650'</u>	<u>1°</u>
<u>2104'</u>	<u>$1 1/2^{\circ}$</u>
<u>2604'</u>	<u>$1 3/4^{\circ}$</u>
<u>2710'</u>	<u>$1 3/4^{\circ}$</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: Area Toolpusher