


OIL CONSERVATION DIVISION
RECEIVED
93 JU 15 AM 8 53

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415
Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-291G Field: Bravo Dome
Location: 1968' FEL X 1938' FNL T21N, R33E, SEC 29, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>459</u>	<u>3/4°</u>
<u>676</u>	<u>1/2°</u>
<u>1146</u>	<u>1°</u>
<u>1620</u>	<u>1°</u>
<u>2120</u>	<u>3/4°</u>
<u>2599</u>	<u>3/4°</u>
<u>2663</u>	<u>5/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.



C. D. Hedgcock
Title: T. R.