

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2132-351G Field: Bravo Dome

Location: 1947' FEL X 1968' ENL T21N R32E SEC 35 UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>459</u>	<u>3/4°</u>
<u>675</u>	<u>1 1/4°</u>
<u>1146</u>	<u>2°</u>
<u>1619</u>	<u>1°</u>
<u>2093</u>	<u>1°</u>
<u>2426</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert E. Perry

O. D. Ledman
Title: I. R.