

Memo

From
R. L. Stamets
Geologist

To: Morad
Martinez, Unit 1 & 2

San Antonio, Texas

Completed June 6, 1959

From the OPR according
to the OPR and Regulations

Kelly Moore and Rader (c) Martinez 1 D 24-20N-26E
Last report September 30, 1955, Form C-105.

Inspection shows that the well is mis-located and is probably located in Unit 2 or 1. The pit is filled and there is very little junk on the location of the tank could not be determined. There is open 7" casing in the hole. The casing is covered by an old can. A rock dropped into the hole for several seconds before striking water. A rock dropped into the casing fell