

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Mae Belcher Trustee				Address 6042B Averill Way, Dallas, Texas			
Lease Lula Gambrel		Well No. 1	Unit Letter	Section 24	Township 20N	Range 26E	
Date Work Performed 3/16/61		Pool Wildcat			County Harding		
THIS IS A REPORT OF: (Check appropriate block)							
☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☐ Other (Explain):							
☒ Plugging ☐ Remedial Work							
Detailed account of work done, nature and quantity of materials used, and results obtained. The hole was filled with heavily laden mud and a 25 sx cement plug was placed at 1450'; pipe was pulled up to 1025' and a 5 sx cement plug was run; balance of 5-1/2" was pulled. A 5 sx plug was run at 825'; pipe was pulled up to 425' and a cement plug was run; balance of 7" pipe was pulled. Spotting a 5 sx cement plug at 245' and balance of 9-5/8" was pulled. A 25 sx top hole cement plug was run with a 4" marker 5' above the ground.							
Witnessed by Burt Dodson			Position Fld. Supt		Company Lea County Casing Pullers		
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY							
ORIGINAL WELL DATA							
D F Elev.		T D		P B T D		Producing Interval	
Completion Date		Tubing Diameter		Tubing Depth		Oil String Diameter	
Oil String Depth		Perforated Interval(s)		Open Hole Interval		Producing Formation(s)	
RESULTS OF WORKOVER							
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover							
After Workover							
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.			
Approved by <i>[Signature]</i>				Name Alan Antweil,			
Title <i>District Engineer</i>				Position Agent			
Date <i>May 14, 1961</i>				Company Mae Belcher, Trustee			