

UNION LAND & GRAZING CO.,
No. 1 Ft. Union
SW 3/4 Sec. 2; T20N; R19E
Mora County, New Mexico

Elev : 8200' approx.
Spud : Aug 10, 1961
*Contr: D & E Well Service,
Artesia, New Mexico
*Rig : Bucyrus Erie L-36
Csg : 10 3/4" @ 87'
w/50 sxs - 2% CaCl

Hole Size: 0' - 74' 15 1/2"
74' - 87' 12 1/2"
87' - 122' 10 3/4"
122' - 1420' 8 1/2"

Aug 8 - Aug 10	M.I.C.T. - R.U.C.T.
Aug 10	Spud @ 4:00 p.m.
Aug 10 - Aug 27	Drlg 0' to 307'
Aug 27 - Sept 1	Shot crooked hole w/3 shots - 20 qts each - total 60 qts nitro (SNG) to straighten crooked hole & drilling out after shot.
Sept 1 - Sept 7	Drlg 307' to 663'
Sept 7 - Sept 9	Set 10 3/4" @ 87' w/100 sxs - 2% CaCl (M.C.C. 5:00 a.m. Sept 8 - 5:00 p.m. Sept 9).
Sept 9 - Sept 29	Drlg 663' to 1420'.
Sept 29- Oct 2	Operations suspended @ noon, Sept 29.
	* Contractor relieved and moved off location Oct 2, 1961.
Present Status	Shut down waiting to resume operations.