


N. M. D. C. C.
Hobbs

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

P. O. Box 997
Roswell, New Mexico
January 11, 1943



Stanolind Oil & Gas Company
Box "F"
Hobbs, New Mexico

Re: Santa Fe 053941

Gentlemen:

Receipt is acknowledged of your "Notice of Intention to Test Water Shut-Off" dated January 7, 1943 covering your Fuller No. 1 well on the subject land in the NE $\frac{1}{4}$ of Sec. 25, T. 8 N., R. 30 E.

The attached notice is approved on the condition that results of the proposed work will be submitted by proper written report to this office within 15 days after completion.

Very truly yours,


John A. Barnett
JOHN A. BARNETT,
District Engineer.

JAB:ls



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

[Faint, illegible handwritten text]



Indian Agency _____

(SUBMIT IN TRIPLICATE)

U. S. Land Office Santa Fe

Allottee _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Lease or permit No. 053941

R.C. Key
Stanolind Oil & Gas Co.
J.W. Fuller (Fee)

Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____		SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	☒	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____		SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____		SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____		SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 9, 1945

Well No. 1 is located 680 ft. from N line and 680 ft. from E line of sec. 28

NE 1/4 Sec. 28

(1/4 Sec. and Sec. No.)

8-N

(Twp.)

30-E

(Range)

N.M.P.M.

(Meridian)

Frio Downs

(Field)

Gray

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 4482.1 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

At 7:00 P.M. January 9, 1945, 72 hours will have elapsed since setting 13" casing at 1084' and cementing to the surface with 500 sacks of cement.

At this time, we plan to test this casing shut-off in the following manner:

Build up 1000# pressure and hold for 30 minutes. If the test is o.k. drill plug, again build up 1000# pressure and hold for 30 minutes. If this too is o.k. drilling will be resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box "F" Hobbs, New Mexico

By Ralph J. Hensel
Title Field Supt.

U.S. Land Office
Bureau of Reclamation
Washington, D.C.
20540

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
SUBMIT IN TRIPLICATE

Indian Agency
Name
Address
Location

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO ABANDON WELL	
NOTICE OF INTENTION TO PUMP OR ALTER CAPACITY	
NOTICE OF INTENTION TO SHOOT OR ACIDIFY	
NOTICE OF INTENTION TO REPAIR OR REPAIR WELL	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	
NOTICE OF INTENTION TO DRILL	
SUBSEQUENT REPORT OF ABANDONMENT	
SUBSEQUENT REPORT OF REPAIRING OR REPAIR	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF SHOOTING OR ACIDIFYING	
SUBSEQUENT REPORT OF WATER SHUT-OFF	

(INDICATE ABOVE BY CHECK MARK WHETHER REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 1/2 mile from line and 1/4 mile from line of section 1, Township 10N, Range 10E, Section 1, T10N, R10E, S1E. The elevation of the derrick floor above sea level is 1118.1 ft.

DETAILS OF WORK

(If the nature of work expected depths to objectives and/or weights and lengths of proposed casing; indicate including job, casing, and other important proposed work)

The purpose of this work is to determine the water level in the well. The work was done on 10/10/1914. The water level was found to be 1118.1 ft. above sea level. The work was done by the U.S. Geological Survey.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company
Address
By
Title