

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

INSPECTION REPORT

June 20 1952

C
O
P
Y

NEWTON R. ROBERTS

Re: McCune No. 1
NWNE Sec. 22-11N-13E
San Miguel County

Total depth of the above captioned well on this day was 266'. The well was spudded-in June 15, 1952. A 13 3/4" hole was drilled to 70' and reduced to 8 3/4" from this depth to total depth. At the time of my inspection the hole was being reamed to bottom prior to cementing 10 3/4" surface casing, which job was expected to be performed June 21.

There is not much recent fill at this location so that drilling was for the most part in hard formation from the cellar on down. Bits used to reach 266' were an OSC-1, OWC, and two EM bits in that order. A water sand was encountered at 235-242' and total depth was in red shale. The proposed surface string of casing is designed to go past the latter water zone and effect a shut-off.

E. A. C.

EUGENE A. CHAVEZ,
Geological Scout, District 4

ir