

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		Report of Setting 234 ft. of surface pipe & cementing	

June 21st. 52

McCune Lease

Date

Place

Following is a report on the work done and the results obtained under the heading noted above at the McCune No. 1

by Newton R. RobertsWell No. 1 in the

Company or Operator

Lease

Mw 1 NE 1 of Sec. 22, T. 11 N, R. 13 East, N. M. P. M.,

Pool San Miguel County.

The dates of this work were as follows: June 21st. 1952

Notice of intention to do the work was (was ~~not~~) submitted on Form C-102 on June 20th., 1952, and approval of the proposed plan was (was ~~not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED
 Set 234 feet of 10 3/4 inch casing (New Casing)
 with new guide shoe.
 Used 175 sacks of cement, (regular)
 Time mixing 30 minutes
 Maximum pressure 100 pounds
 Weight of casing 47 lbs.

Witnessed by

Name

N.R. Roberts

Company

Tool Pusher

Title

APPROVED:

OIL CONSERVATION COMMISSION

Eugene A. Chavez

Name

geologist

Title

Date

June 30, 1952

I hereby swear or affirm that the information given above is true and correct.

Name

Position Tool Pusher

Representing

N.R. Roberts

Company or Operator

Address

Zia Lodge, 4611 East Central
Albuquerque, N.M.