

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

INSPECTION REPORT

August 1, 1952

C
O
P
Y
NEWTON R. ROBERTS

Re: Roberts No. 1 Aaron
SWSW Sec. 14-11N-15E
San Miguel County

The above captioned well was spudded July 29, 1952 and drilled the following section prior to setting surface string:

0 - 120'	Red sand
120 - 162'	Sand & shale
162 - 188'	Hard sand
188 - 193'	Sand and shale

10 3/4" casing was cemented at 190' with 100 sacks. This job was completed at 11:10 p.m., July 31 and the well was standing cemented at the time of my inspection today.

Circulation was lost at 120' and the mud had to be treated with 68 sacks of gelflake, 20 sacks of clay, 31 sacks of cottonseed hulls, and 13 sacks of crevice seal during penetration from this depth to 188'.

This location is reached by turning north from U. S. Highway 66 at state road No. 3, 13 miles east of Clines Corners. Thence proceeding north on No. 3 for sixteen miles and then turning east (right) on the open range for six miles to the well site. The latter six miles is not due east but winds through hilly and flat country. There are two gates to open.

E.A.C.

EUGENE A. CHAVEZ,
Geologist - District 4