

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

COPY

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator M. A. ROMERO		8. Farm or Lease Name SAM SHAW
3. Address of Operator 1419 Madrid Rd., Box 5155, Santa Fe, NM 87502		9. Well No. 2
4. Location of Well UNIT LETTER <u>P</u> <u>535</u> FEET FROM THE <u>East</u> LINE AND <u>337</u> FEET FROM THE <u>South</u> LINE, SECTION <u>13</u> TOWNSHIP <u>4N</u> RANGE <u>7E</u> N.M.P.M.		10. Field and Pool, or Whdcat
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Torrance

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER <u>Waiting rig from Shaw No 3</u> ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well drilled to depth of 1850 and logged by Schlumberger to depth of 1842 feet.

Drilling resumed on Dec. 11th and carried to total depth of 2841 feet, and logged by Schlumberger to 2820 feet.

On Dec. 23rd 1979 well was plugged solid by National Cementers Corp., Grants, NM from bottom to 1940 feet.

On Dec. 27th 4½ 12 lb casing was set at 1900', cemented by National Cementers Corporation.

Dalton Logging and Perforating Co., Grants, NM logged before perforating zones showing promise of oil or gas.

After perforating well was acidized and was swabbed. We obtained a return of water and acid placed in well.

As of today we have suspended work and are awaiting completion of SHAW NO. 3 well, and have the RAF Corporation engineers assist us in completing Shaw No. 2.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Romero TITLE Operator DATE 5-1-80APPROVED BY Carl Ulvay TITLE SENIOR PETROLEUM GEOLOGIST DATE 5/23/80

CONDITIONS OF APPROVAL, IF ANY: