

NEW MEXICO OIL CONSERVATION COMMISSION


Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING OR OTHERWISE ALTERING CASING
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	✓	REPORT ON PULLING OR OTHERWISE ALTERING CASING
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	✓	REPORT ON DEEPENING WELL
REPORT ON RESULT OF PLUGGING OF WELL	✓	



Estancia New Mex Place May 26-41 Date

OIL CONSERVATION COMMISSION, SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Drice Company Company or Operator Well No. 1 in the _____

of Sec. 32 T. 7N, R. 7-E, N. M. P. M., Estancia Valley Field, Torrance County.

The dates of this work were as follows: Mar-11-41 to April 7-41

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____ 19____ and approval of the proposed plan ~~was~~ (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

6 5/8" casing was set, landed + cemented at 1428 ft. Drilled out plug and found to be dry. 5 1/2" casing landed and cemented at 1939 ft. 2 in. Drilled out plug and tested formation at 1965 ft. to 1989 ft. No production of e.o.o. A little color of oil on the water. Drilled to 2062 ft. no further showing. after shooting well from 1965 to 1989 ft. found no showing. Cut off 5 1/2" casing at 1450 ft. Pulled out. Plugged 5 1/2" casing with wooden plug. cemented with 2 sacks of cement. Cut off 6 5/8" casing at 1250 ft. Pulled out cemented, drove in wooden plug. cemented using 2 sacks of cement. Pulled 8" casing at 765 ft. Plugged 10" casing at 65 ft. and left 10" in hole.

Witnessed by Wm Woodruff Name Drice Co. Company Seely Title

Subscribed and sworn before me this 1st day of July, 1941
Frances Ward Notary Public
My commission expires Apr. 4. 1944

I hereby swear or affirm that the information given above is true and correct.
Name Wm Woodruff
Position Deputy
Representing Drice Co Company or Operator
Address Albuquerque, N.M.

Remarks:
Very thorough Name
Title