

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Amoco Production Company	7. Unit Agreement Name BDCDGU
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	4. Location of well UNIT LETTER <u>G</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>30</u> TOWNSHIP <u>24-N</u> RANGE <u>33-E</u> N.M.P.M.	8. Farm or Lease Name BDCDGU 2433
5. Elevation (Show whether DF, RT, CR, etc.) 5260' GL	6. County Union	9. Well No. 301
10. Field and Pool, or Locality Und. Tubb		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposals or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 8-14-81 Aztec Drilling (rig #50) spudded a 12-1/4" hole at 7:00 pm. Drilled to a TD of 282'. Kelly bushing fell, hit slips, and knocked drill collars in hole. Pulled drill collars and bit to 122' and stuck. Knocked bit down to 145' and unable to pull up past 145'. Ran free point and stuck bit at 168'. Backed off at 164'. Left bit and 4' bit sub in hole. Recovered all drill collars. Ran drill pipe to 160'. Cemented hole to surface with 250 sacks class H and 2% CACL. Pulled drill pipe and filled hole to surface with cement. Rigged down and skidded rig off hole 35' to the west. Installed PXA marker.

- 0+2-NMOCD,SF 1-HOU 1-SUSP 1-CLF 1-Amerada 1-Amerigas 1-Cities Serv.
1-Conoco 1-CO2 in Action 1-Excelsior 1-Sun. Tex.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Cathy L. Forman TITLE Assist. Admin. Analyst DATE 1-19-83

APPROVED BY _____ TITLE _____ DATE 1/24/83

CONDITIONS OF APPROVAL, IF ANY: