

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2134-291K Field: Bravo Dome

Location: 1966' FWL x 2006' FSL T21N, R34E, SEC 29, UNIT K

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>409'</u>	<u>1/4°</u>
<u>695'</u>	<u>1/4°</u>
<u>1141'</u>	<u>1/2°</u>
<u>1613'</u>	<u>1 3/4°</u>
<u>2061'</u>	<u>1 1/4°</u>
<u>2560'</u>	<u>2°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Larry J. Young

Kurt Stahmer
Title: Area Toolpusher