

OIL CONSERVATION DIVISION
AUG 9 08


INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415
Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 8232-246 Field: Bravo Dome
Location: 2005' FEL X 1974' ENL T22N, R32E, SEC 26, UNIT 9

DEPTH	ANGLE INCLINATION DEGREES
<u>459</u>	<u>1/2°</u>
<u>245</u>	<u>1/2°</u>
<u>689</u>	<u>1/2°</u>
<u>1149</u>	<u>1/2°</u>
<u>1623</u>	<u>3/4°</u>
<u>2097</u>	<u>3/4°</u>
<u>2350</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: SITON Tool Pusher