

OIL CONSERVATION DIVISION
RECEIVED

INCLINATION REPORT

'93 JUN 14 AM 9 21

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233 281F Field: Bravo Dome

Location: 1909' FWL x 1903' FNL, T22N, R33E, SEC 28, UNIT F

<u>DEPTH</u>	<u>ANGLE</u> <u>INCLINATION DEGREES</u>
<u>246</u>	<u>.25</u>
<u>680</u>	<u>.25</u>
<u>1161</u>	<u>.25</u>
<u>1634</u>	<u>.25</u>
<u>2013</u>	<u>.25</u>
<u>2153</u>	<u>.50</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Lang J. Young (Amoco)

Bobby Denny
Title: SITON TOOLPUSHER