

'93 JUN 10 AM 8 43

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233 331 G Field: Bravo Dome

Location: 1999' FEL x 2012' FNL, T22N, R33E, SEC 33, UNIT G

<u>DEPTH</u>	<u>ANGLE INCLINATION DEGREES</u>
<u>385'</u>	<u>1/2°</u>
<u>688'</u>	<u>3/4°</u>
<u>995'</u>	<u>3/4°</u>
<u>1495'</u>	<u>3/4°</u>
<u>1955'</u>	<u>3/4°</u>
<u>2114'</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Carman - Amoco

Walt Satter
Title: ARTEC TOOL FISHER