

OIL CONSERVATION DIVISION
RECEIVED

'93 JUN 21 AM 8 55

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2233-34/G Field: Bravo Dome

Location: 1909' FEL X 2099' FNL, T22N, R33E, SEC 34, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>215'</u>	<u>1/4°</u>
<u>462'</u>	<u>1°</u>
<u>680'</u>	<u>1°</u>
<u>1123'</u>	<u>1 3/4°</u>
<u>1596'</u>	<u>1 1/2°</u>
<u>2038'</u>	<u>1 1/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Ronnie R. Camacho

Bob Dandy
Title: SITON Tool Pusher