

INCLINATION REPORT


Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2232-351F Field: Bravo Dome

Location: 2150' FWL X 2000' FNL T22N, R32E, SEC 25, UNIT F

DEPTH	ANGLE INCLINATION DEGREES
<u>215</u>	<u>1/4</u>
<u>460</u>	<u>3/4</u>
<u>690</u>	<u>3/4</u>
<u>1119</u>	<u>3/4</u>
<u>1593</u>	<u>1°</u>
<u>2066</u>	<u>1°</u>
<u>2275</u>	<u>1°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.




Title: SITON Tool Pusher