

NEW MEXICO OIL CONSERVATION COMMISSION						FORM C-103 (Rev 3-55)	
MISCELLANEOUS REPORTS ON WELLS						1117 12	
(Submit to appropriate District Office as per Commission Rule 1106)							
Name of Company Morad Oil & Gas Co.				Address Roy, New Mexico			
Lease P.T. Campbell		Well No. 1	Unit Letter A	Section 25	Township 28N	Range 25E 35E	
Date Work Performed May 20, 1959		Pool			County Union		
THIS IS A REPORT OF: (Check appropriate block)							
☐ Beginning Drilling Operations		☐ Casing Test and Cement Job		☐ Other (Explain):			
☒ Plugging		☐ Remedial Work					
Detailed account of work done, nature and quantity of materials used, and results obtained.							
Set a cement plug from 275 feet to 175 feet and filled the hole with drilling muf up to 75 feet. Set another cement plug from 75 to 50 feet and filled the hole with drilling mud up to 15 feet. Set a cement plug from 15 feet to the surface and set a four-foot high well marker with a four-inch diameter in this upper plug. Pits are filled and the location leveled and cleared of all junk.							
Witnessed by P.T. Campbell		Position Owner		Company			
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY							
ORIGINAL WELL DATA							
D F Elev.		T D		P BTD		Producing Interval	
Completion Date		Tubing Diameter		Tubing Depth		Oil String Diameter	
Oil String Depth		Perforated Interval(s)		Open Hole Interval		Producing Formation(s)	
RESULTS OF WORKOVER							
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover							
After Workover							
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.			
Approved by				Name Rudy Paul			
Title				Position Driller			
Date				Company			

Form C-103 (3-22-56) signed by C. B. Miller

(6)

Morad Oil and Mining Company - Roy, New Mexico
O. T. Campbell 1 A 25-28N-35E

Last report, drilling at 600 feet received, March 30, 1956.

Inspection shows that the pits are not filled, that there are two strings of casing in the hole, that the ground is caving around the hole becoming a menace to cattle and that there is some junk and 3 or 4 strings of 7 inch casing on the location.

ILLEGIBLE

6-2-77 Took pictures, and samples of the ... (Black hole) in ...
was ... (374-2485)

Can there be ... (at T.D. ... forced plugging ... before action taken).

Black hole ... (biting center) ...

... (to old man) ...

... (well and ...)

... (10 ...)

10 ...

OH to ...

... (240 to 245)

... (200 deep) ...

...

...

...

...