

OIL CONSERVATION COMMISSION
P. O. BOX 871
SANTA FE, NEW MEXICO

INSPECTION REPORT

May 14, 1952

C
O
P
Y

HARRY C. LONG

Re: Dalies No. 1 (formerly
Sunol No. 1) Sec. 32-7N-1E
Valencia County

On this day I witnessed the plugging of the above captioned well. The hole was plugged back from 1445' to 1319' with 65 sacks of common cement. A maximum pump pressure of 100 p. s. i. was used for the job which was done by the Halliburton Company.

208' of 10 5/8" casing has been left cemented in the hole and a 10 sack cement plug will be set manually at the surface.

E. A. C.
E. A. CHAVEZ,
Geologist

ir