

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: Poker Lake Unit 89	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-27787
------------------------	------------------------	-----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	25	24S	30E	2310	North	1980	East	Eddy

Latitude: N 32° 11' 23.18" Longitude: W 103° 49' 55.56"


### NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 1 bbl crude oil and 13 bbls PW	Volume Recovered: 1 bbl PW
Source of Release: 1/4" hose	Date and Hour of Occurrence: 7/3/14 time unknown	Date and Hour of Discovery: 7/3/14 @ 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~380 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		

**Describe Cause of Problem and Remedial Action Taken.\*** A 1/4" hose going from the wellhead to the high pressure kill switch was damaged by livestock. The hose was replaced with stainless steel tubing.

**Describe Area Affected and Cleanup Action Taken.\*** The spill impacted approximately 4,180 sq. ft. of caliche pad. The free standing fluid was recovered and soil samples collected. All contaminated soil has been removed and hauled for disposal. The area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines and backfilled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins		Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman		Approval Date: 9/19/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com		Conditions of Approval:	
Date: 9-12-14 Phone: (432) 214-3704		final	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary