

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Bopco, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329	
Facility Name: Poker Lake Unit 227 Tank Battery	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-33929

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	30	24S	30E	330	South	560	East	Eddy

Latitude: N 32° 10' 54.54" **Longitude:** W 103° 54' 48.19"

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 6 bbls	Volume Recovered: 1 bbls
Source of Release: process separator	Date and Hour of Occurrence: 7/3/14 time unknown	Date and Hour of Discovery: 7/3/14 @ 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~260 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Cows broke a 1/4" fitting off of one of the process separators. The fitting was replaced and a fence was installed around the process equipment.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 350 sq. ft. of caliche pad. The free standing fluid was recovered and soil samples collected. All contaminated soil has been removed and hauled for disposal. The area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines and backfilled.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Brad Blevins		Approved by District Supervisor:
Title: EHS Asst. Remediation Foreman		Approval Date: 9/19/2014 Expiration Date: NA
E-mail Address: bblevins@basspet.com		Conditions of Approval:
Date: 9-12-14 Phone: (432) 214-3407		NA FINAL Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary