

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/8/2014

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. (575)-738-1739
Facility Name: Turner Skelly #26	Facility Type: Injection

Surface Owner Federal	Mineral Owner Federal	API No. 300150515
-----------------------	-----------------------	-------------------

LOCATION OF RELEASE

Unit Letter J	Section 15	Township 17S	Range 31E	Feet from the 1880	North/South Line South	Feet from 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-------------------	------------------------	-------------

Latitude: 32.8325111956535 Longitude -103.855428013811

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 30	Volume Recovered 0
Source of Release: Steel pipeline	Date and Hour of Occurrence 04/04/2012 9:30 AM	Date and Hour of Discovery 04/04/2012 10 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher NMOCD- Terry Gregston BLM	
By Whom? Joe Hernandez	Date and Hour: 04/05/2012 4:39 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* NA

Describe Cause of Problem and Remedial Action Taken.* Production Foreman drove to the location and discovered injection line leaking and shut in the well.

Describe Area Affected and Cleanup Action Taken: DFSI was retained to fully remediate the site according to NMOCD and BLM guidelines and respectfully request closure of this incident.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature: <i>Fred B Wall</i>		Approved by Environmental Specialist:	
Printed Name: Brian Wall			
Title: Construction Foreman II		Approval Date: 10/23/2014	Expiration Date: NA
E-mail Address: bwall@linenergy.com		Conditions of Approval: FINAL	
Date: 09/17/2014 Phone: 806-367-0645			
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1115