

**From:** [Blevins, Bradley](#)  
**To:** [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)  
**Cc:** [Daniel Dominguez \(ddominguezepi@gmail.com\)](#); [Blevins, Bradley](#)  
**Subject:** PLU Big Sinks 7-25-31 (PLU CVX JV Big Sinks 17H)  
**Date:** Thursday, October 09, 2014 9:54:10 AM

---

Mike/ Heather

Per our meeting on Tuesday, October 7<sup>th</sup> concerning the remediation activities on the PLU Big Sinks 7-25-31. Sample points one through three were excavated to a depth of one foot bgs, sample point four was excavated to a depth of two feet bgs. By doing so all concentrations of concern were removed from the release area. Sample points five through seven were over spray areas and were blended below OCD remedial thresholds. Sample point five surface level TPH was discussed with Mike and was approved. Two initial C-141's were filed on this location and both have been addressed, (6-17-14 & 7-10-14). An email approval of these items will be greatly appreciated, if you have any questions please let me know. Daniel with EPI will follow up with the closure report. Thank you for taking the time to meet and discuss this project.

Brad Blevins  
Assistant Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)