

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: PLU-JV-CVX-Big Sinks #017H AKA PLU Big Sinks 7-25-31 USA #1H - Area 2	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-40447
-------------------------------	-------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E					Eddy

Latitude: N 32.151831 **Longitude:** W 103.818964

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 12 bbl water and 8 bbls crude oil	Volume Recovered: none
Source of Release: Free water knockout sight glass.	Date and Hour of Occurrence: prior to 6/17/14	Date and Hour of Discovery: 6/17/14 @ 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

Depth to Water. ~420 ft bgs


If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

The release area was discovered by a BOPCO Lead Pumper. It appeared that the sight glass had been broken and repaired.

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 900 sq. ft. of tank battery pad. The release also misted approximately 4,500 sq. ft. of pasture area that had been cleared of vegetation during the tank battery pad construction. The spill area has been cleaned up in conjunction to another reportable spill at this location. The contaminated soil has been removed and hauled to state approved facility for disposal, and the excavation backfilled with clean soil. The pasture area has been blended with clean soil in the immediate vicinity in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS.Asst.-Remediation Foreman	Approval Date: 11/5/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-14-14 Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary