

Received 10/30/2014

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: Poker Lake Unit 423 Tank Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-40710
-------------------------------	-------------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	19	25S	30E	1750	South	880	East	Eddy

Latitude: N 32° 6' 47.64" Longitude: W 103° 54' 54.89"

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 140 bbl crude oil and 280 bbls PW	Volume Recovered: 100 bbls crude oil 220 bbls PW
Source of Release: Failed gasket on hatch cover on the free water knock out.	Date and Hour of Occurrence: 7/27/14 time unknown	Date and Hour of Discovery: 7/28/14 @ 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD and Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour: 7/28/14 @ 3:08 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

Depth to Water. ~250 ft bgs

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

A gasket failed on the man way cover on the free water knock out. The production was switched out of the vessel and vacuum trucks were dispatched to the location.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 8,616 sq. ft. of earthen containment area around the process equipment, approximately 200 sq. ft. of pad area, and approximately 800 sq. ft. of pasture area on the west side of the pad area where the containment breached. All of the free standing fluid was recovered and placed back into the production tanks. A remediation crew from EPI began removing the saturated soil from around the process equipment and stockpiling soil on-site. On 7/31/14 a backhoe was used to collect samples for vertical extent in six areas around the release area. Contaminated soil has been excavated and hauled to a state approved disposal facility and the excavation has been backfilled. The impacted area complies with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 11/5/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>10-14-14</u> Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2413